

SITE INVENTORY

(Border marker S55 at Mt Franklin; see site 26 in the inventory)

Earlier interest in the border markers

Before fieldwork to locate original markers could begin, it was necessary to not only research the surveyors' fieldbooks so as to ascertain what forms the markers took, but also to establish whether any work had since been done to refurbish or replace original markers with later ones.

A plan to refurbish the border markers arose in the Australian Survey Office (ASO) in the late 1970s. First in 1977 and then in more detail the following year, John Hyslop suggested that, as the markers had been subjected to several deleterious impacts, the border should be re-marked, with surviving markers being located and retained, and lost or damaged markers being replaced with new ones. Hyslop listed four main impacts on the border: the clearing of a major firebreak down the Brindabellas (on the western boundary), the burying of various markers along the railway line, development between Queanbeyan and Oaks Estate, and replanting of Kowen Forest (all on the north-eastern and eastern boundary). He estimated that 650 metres could be traversed and relocated each day, he costed the project, prioritised the various sections of the whole border, and then recommended that a reconnaissance be conducted. The idea seemed to find favour; Jack Taylor late in 1978 commented on the 'devastation' caused on the western boundary by the firebreak clearing in the early 1950s.

Various ideas were put forth for the form of the re-marking. In some instances the new marker would be of the same type as the original, while in others concrete posts etc were suggested, and additional marks were also conceived.

By mid 1978 a reconnaissance had been conducted by John Wenborn. Sampling various sections of the border as vehicle access determined, he listed the condition of markers. Regarding the southern and western boundary (the borders chosen as the area of fieldwork for this present project), Wenborn generally found the southern and south-western areas relatively undisturbed (especially the latter), but found that markers in the section from Mt Franklin north to Mt Coree had been severely damaged by the firebreak.

The ASO's Special Projects Section was to tackle the job. Meanwhile, new markers were being added to the border anyway. In 1980 a NSW subdivision survey adjacent to part of the border saw that section re-marked with 75mm pegs, and in the same year on Portion 33, Parish Amungula (on the north-eastern border), some original pegs were lost to a firebreak, with some being replaced with 75mm pegs.

Negotiations with the NSW survey authorities to obtain a bipartisan approach proceeded. But that is as far as the project got. On 29 April 1981 D.P.Cook of Special Projects wrote on file that the proposal had been deferred indefinitely, owing to the fact that the NSW Government had not agreed to go ahead. It is understood too that funding for such a project would have been in short supply by the early 1980s.

So no refurbishment program was undertaken. As mentioned however, later survey pegs have in places been installed on the border, and the present fieldwork along the western and southern boundary revealed several such new pegs.

The fieldwork

The fieldwork for the project covered the ACT-NSW border from Mt Coree to the Bobeyan (nowadays written Boboyan) Road, a distance of almost 100 kilometres or a little over one third of the entire boundary. This section contains the highest and most rugged part of the boundary.

The fieldwork occupied about thirty days scattered mainly through autumn 1996, finishing in early winter before heavy snow could interrupt the work. The first four days employed conventional survey methods (theodolite, ranging pole and electronic distance measurer or EDM) and extended from Mt Coree to Piccadilly Circus. Lithgow surveyor John Stevens operated the equipment and I acted as chainman and recorded the sites discovered. On the fifth day (taking the work south to Bulls Head), the technique was employed which had been planned for use during the majority of the rest of the work. This consisted of using the FC18 map sheets along with compass and topographic map. Some of the FC18 sheets contained the bearings and distances between markers and also the types of markers, and where they didn't this data was copied across from the fieldbooks. Distance was measured by pacing. Once the distance to the stated site of a marker had been paced, either the marker was immediately found or a plastic tag was placed at that point and a considerable area around the tag was searched for the border marker. Then either the marker was found or a decision was made that it was gone or could not be located and the tag was retrieved, the bearing was set to the next marker and the pacing began again.

After John's departure, as planned I continued the work mostly alone in a series of day trips which saw the fieldwork push south to Rolling Ground Gap. During this time, Russell Wenholz, Kevin Freund and Ray Griffiths from the ACT Land Information Office spent a day with me using Global Positioning System (GPS) equipment to try to locate two markers near Piccadilly Circus which had not been previously located and also to test the location of a found marker on Mt Ginini which was loose on the ground and may not have been in its true location. On Mt Ginini (where, incidentally, a few inches of early snow lay on the ground and surrounding trees), the GPS was effective, but in regard to the other work, despite hours spent using the GPS, its results were inconclusive. (Kevin Freund subsequently returned to the area and by conventional methods confirmed the site of at least one of the markers; see site 8A in the inventory.)

Russell Wenholz later accompanied me for a day on Gingera and subsequently during a re-walk of part of the Bobeyan Divide. Stephanie Haygarth came with me to re-walk part of Ginini, and Stan Goodhew likewise joined me during a return visit to Mt Franklin at the very end of the work.

From Rolling Ground Gap most of the work was beyond vehicle-based walking access and field trips became camping trips, starting from the nearest access point. A five-day trip began at the Ginini locked gate (joining the border at Rolling Ground Gap) and covered the boundary through over Mt Bimberi and to the lower northern flank of Mt Murray. A three-day trip, beginning below Yaouk Gap, then covered the section from Mt Murray to the north-western peak of the Mt Scabby bowl. Both of these trips were undertaken by me on my own. The third overnight trip, of five days, began and ended at the Bobeyan locked gate and covered the border from Scabby over Mt Kelly to the point where the Sams River Firetrail crosses the border east of Sams River; on this trip I was accompanied by bushwalking friends Ian McLeod and David Cregan. A day trip (on my own) then covered the Bobeyan Divide west from the Bobeyan Road almost to the head of Grassy Creek. The last overnight trip began and ended at the Bobeyan gate and covered the border from the Sams River Firetrail up over much of Sentry Box Mountain, and a little of the area near the head of Grassy Creek; John Stevens and Ian McLeod again participated. A final day trip (with Ian) linked the section between Sentry Box and Grassy Creek and completed the fieldwork (at last!).

In planning these camping trips it was early decided that the search for markers would best be done lightly equipped, for carrying a full pack through difficult country (especially on steep inclines) is not conducive to following a bearing with the high level of accuracy required by this work. Consequently base camps were used where possible. While this meant that a good deal of time was spent returning to camp at the end of a day, and in some instances rewalking searched areas the next in order to get to the beginning of that day's work, this was considered preferable for the sake of

accuracy. During the day trips too it was of course necessary to walk considerable distances back to the car on most days. Certain sections of the border were visited more than once (eg Piccadilly Circus, Franklin, Ginini, Little Ginini, the Bobeyan Divide) and were re-walked for increased accuracy. The total distance walked during the project is more than three times greater than the almost 100 kilometres that the section of the border measures.

While I gratefully accepted accommodation at Bendorra Dam provided by Namadgi National Park at the beginning of the fieldwork, I did not wish to make demands of the Park further south. Consequently no requests were made for rides in Park vehicles — or helicopters that might have been operating in the area — in order to ease the access problems associated with the overnight trips. Besides, to have done so would have been out of keeping with the spirit of the project.

The site inventory forms should be self explanatory. The forms, in addition to displaying the site numbers used for the project, also show the surveyors' original station number. The use of a six-figure grid reference for such small sites is a crude method of defining location, so copies of topographic maps showing the site numbers have also been included. The type of marker shown on the form is that which is either visible at the site, or, where the marker itself (as opposed to the accompanying rockspit and/or reference tree) cannot be seen, the type is that which is described in the fieldbook. While extant timber post markers are usually visible, iron pipes and other metal and concrete markers are not always so easy to see in or under the rockspit or cairn. Where the marker is visible, or where it can be glimpsed by lifting two or three of the central stones of the rockspit and scraping aside soil and leaves (remembering that the markers were often buried flush with — or below — ground level), it is said to be visible in the 'comments' section of the form (this does not necessarily mean it is visible in the accompanying photo). Where it cannot be seen (because it is buried too deeply or has gone), it is said to be not visible, and where it clearly seems to have gone, this is stated. Although normal survey practice is to keep digging until the marker is found, this was generally not practised under the project as it was desired not to cause any sort of substantial disturbance to the sites. Each site was left in the same condition as it was found, though fallen bark, branches etc were in most instances removed.

A site makes sense to the eye when viewed in three dimensions, but trying to convey the site's essence through a two-dimensional photograph is often difficult (especially when the site in question is small and surrounded, or partly covered, by vegetation). For this reason arrows have been drawn onto some of the pictures to aid their interpretation by users of this report. Some of the arrows point to specific features. Others are designed to allow readers to more easily see the orientation of the rockspits along the ground; sometimes these arrows reflect the rockspits' acute changes in bearing about the markers, though more subtle changes of bearing are not necessarily shown, and some of these arrows simply show the direction of the portion of the rockspit that is visible in the photo.


A healthy degree of scepticism was employed during the fieldwork. A line of stones was not immediately accepted as a rockspit. Stones can occur in lines naturally, and in the area of the border affected by bulldozing it was even more important not to reach hasty conclusions. It was felt that it was better to rule out a small number of potential (but not proven) sites rather than to include them in the inventory and so lower the integrity of the inventory. Potential border markers which were thus not included are T53, H55, R56, R73, M74, G79, Y79, Z85, O86, A87, M41, S41, T41, O42, W42 and X42. Similarly, reference trees were closely scrutinised. Where the original survey markings were present there was of course no question about accepting the tree, but markings do weather away and can be burned off and so where only a blaze was present it required further examination. There are huge numbers of natural tree scars in the bush (caused by fire, dropping of branches, dozer scrapes next to trails etc) and

while most are quite different to survey blazes some are surprisingly similar. Many sorts of blazed trees other than border reference trees were seen during the fieldwork, cut by surveyors and others. Where only a blaze remained on a tree it was accepted as a border reference tree only if it was at the correct bearing as indicated in the fieldbooks.


A total of 272 markers was found during the fieldwork. Out of c.740 markers originally installed between Mt Coree and the Bobeyan Road, this represents 37%, or better than 1 in 3, which was many more than I had anticipated finding. There are various reasons for the loss of markers. The 1950s firebreak is a major cause of loss in the northern half of the Brindabellas. It extended from the southern foot of Coree right to Mt Franklin and then reappeared for a distance on Ginini. It is a swathe some 35 metres and more in width and is still easily seen. Road-building, powerline-clearing, fencing and ski-run clearing also have taken their toll. Bushfire and natural decay have seen the demise of reference trees and timber markers, and some of the metal markers may have rusted away (galvanised iron does rust in time, given certain conditions). Galvanised pipe markers placed in acidic soils may also have corroded away. Souveniring of markers and interference or vandalism too have had their impact. It is known that some ACT border markers have been deliberately taken. At least one marker on the southern border rubbish was found under the rockspit, indicating interference. At another the concrete cylinder marker has been moved outside of the rockspit. On part of Mt Scabby a marker appears to have been entirely removed and only the 'silhouette' of the rockspit's discolouration on the supporting granite slab remains. Near the summit of Bimberi, where there should have been a marker, the rockspit seems to have been adapted into a shelter wall for a bushwalker's fire and campsite. The terrain of the border too is a factor. Steep, rocky, heavily vegetated mountainsides exposed to the vagaries of mountain weather are not the easiest places on which to find border markers. Some markers may well have been missed during the fieldwork, although very great efforts were made to find all of them. (This report should not be viewed in the same legal light as a survey report by a licensed surveyor.) As is mentioned later, anyone finding additional markers is encouraged to report them to the relevant authorities.


A map of the fieldwork area, the set of above-mentioned topographic maps, and the site inventory forms now follow. (Several sites of possible Aboriginal significance were seen during the fieldwork and information concerning these will be gladly passed on to Park staff on request.)


SECTION OF ACT BORDER COVERED BY FIELDWORK



SITE NUMBERS AND THEIR LOCATIONS









148°45'00"

PICCADILLY CIRCUS 21km


35°30'00"


659


59d


61


62
















SCALE 1:25000

CONTOUR INTERVAL 10 METRES









ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 1

CMA 1:25,000 map name: Cotter Dam.....

Grid reference: 644911.....

Original station number: A50a.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Top of post burnt; markings 'CT' visible (see → in photo) and '↑' partly visible. The fieldbook states that only '↑' was inscribed, perhaps suggesting that communications with Mount's party were still settling down at this very early point in the survey. A red, plastic tag has been left at the site by a recent surveyor.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 2

CMA 1:25,000 map name: Cotter Dam

Grid reference: 643909

Original station number: A50

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post is partly rotten and fallen. No markings visible, though axe marks from sawing off post can be seen. A red plastic tag has been left at site by a recent surveyor.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 3

CMA 1:25,000 map name: Cotter Dam

Grid reference: 643908

Original station number: 350

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post is very rotten, and fallen. A red plastic tag has been left at the site by a recent surveyor.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 4

CMA 1:25,000 map name: Cotter Dam.....


Grid reference: 642907.....

Original station number: C50.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post is partly burnt; rockspit notable for large size of stones. Post is quite tall.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 5

CMA 1:25,000 map name: Cotter Dam.....

Grid reference: 642 906.....

Original station number: D50.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post is extremely vestigial - rotten and fallen.
Part of the 'C' marking (from 'CT') is visible,
as is another mark, possibly part of the 'T' (see photo).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 6

CMA 1:25,000 map name: Cotter Dam

Grid reference: 629 877

Original station number: R50

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: A
C

Comments: The tree has been partly burnt, the bushfire obliterating part of the original blaze. (→ in photo indicates 'A'; 'C' indicates 'C'). Original blaze would have been marked 'B'.
CT





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 7

CMA 1:25,000 map name: *Cotter Dam*

Grid reference: *631868*

Original station number: *V50*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post is evidently rotting from below, hence its shortness. Marking 'A' is partly visible. (→ photo).





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 8

CMA 1:25,000 map name: Cotter Dam

Grid reference: 634-861

Original station number: Z50

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Tree has been bulldozed and burnt. (→ in photo indicates '↑'; >> indicates 'CT'). A later blaze has also been cut in the tree, and nearby are a later 3" x 2" survey peg (numbered 458) and an indication stake).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 8A

CMA 1:25,000 map name: Cotter Dam.....

Grid reference: 635850.....

Original station number: H51.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post has gone; rockspit only remains. Possible reference tree (markings gone) lies nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 9

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 621777.....

Original station number: R53.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post is evidently rotting from below, hence its shortness. Blaze on reference tree almost closed, no markings visible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 10

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 614 770

Original station number: 11 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

45
R
M

Comments: One of the rare remaining mile reference trees cut...
by Mouat's party (the mile marker itself, to which the tree refers,
appears to have gone). This is at the 11 mile point (11 miles from
Canberra), and half of the '11' has gone. The markings display
considerable skill on the part of the man who chiselled them.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 11

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 609758.....

Original station number: C54.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT

Comments: Tree has been burnt and has broken in two, but markings are still in good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 12

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 609.757


Original station number: D.54

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post rotten and fallen; part of '↑' visible (→ in photo). Later indication stake nearby (» in photo) — evidently placed by a Subsequent surveyor.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 13

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 609756.....

Original station number: E 54.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post gone; rockspit remains. An indication stake left by a later surveyor is present. The blaze in the reference tree has rotted out.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 14

CMA 1:25,000 map name: Tidbinbilla


Grid reference: 608 755

Original station number: F54

Type of marker:

- (8" timber post, with rockspit
- (1" pipe, concreted, with nail, and rockspit
- (3" downpipe, concreted, with bolt, and rockspit
- (nail in concrete, with rockspit
- (spike in concrete, with rockspit
- (concrete block, with bolt, and rockspit
- (concrete cylinder [can formwork], with nail, and rockspit
- (old peg or post, and rockspit
- (reference tree, marked thus: 1
C7

Comments: Blaze on reference tree has partly closed, obscuring the markings. Post gone but rockspit and a later indication stake are visible. Markings on tree would originally have been 'A' C7.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 15

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 611749

Original station number: J54

Type of marker:

- (8" timber post, with rockspit
- (1" pipe, concreted, with nail, and rockspit
- (3" downpipe, concreted, with bolt, and rockspit
- (nail in concrete, with rockspit
- (spike in concrete, with rockspit
- (concrete block, with bolt, and rockspit
- (concrete cylinder [can formwork], with nail, and rockspit
- (old peg or post, and rockspit
- (reference tree, marked thus: 

Comments: Reference tree partly burnt, hence 'C' gone from markings. Rockspit visible but post gone (probably burnt).





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 16

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 608743.....

Original station number: M54.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post rotten and fallen, 'A' partly visible (→ photo).
Rockspit visible. Blaze on reference tree has closed.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 17

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 608741

Original station number: P54

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: (see next page)

Comments: Post in reasonable condition (in foreground of photo); '↑' is just visible on post. Just behind marker is 13 Mile point and one reference tree doubles for both; the tree is in the background of the photo. See next page for further details.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 18

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 608741


Original station number: 13 Mile


Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

45
R M
13
CT

Comments: The downpipe is the 13 Mile marker, and the markings on the reference tree are in good condition. Left photo shows marker; right shows tree. The tree is one of only 3 intact mile trees from Movat's section of the border found during the fieldwork.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 19

CMA 1:25,000 map name: Tidbinbilla.....


Grid reference: 607739.....

Original station number: Q54.....

Type of marker:

- () 8" timber post, with rockspit
- () 1" pipe, concreted, with nail, and rockspit
- () 3" downpipe, concreted, with bolt, and rockspit
- () nail in concrete, with rockspit
- () spike in concrete, with rockspit
- () concrete block, with bolt, and rockspit
- () concrete cylinder [can formwork], with nail, and rockspit
- () old peg or post, and rockspit
- () reference tree, marked thus: 

Comments: Post (\rightarrow right photo) is largely demolished by fallen tree. Markings on reference tree (left photo) weathered but legible.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 20

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 605 739.....

Original station number: R54.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑

Comments: Post rotting from below; '↑' partly visible (see left photo). Reference tree markings are in very good condition. (Top of post is also just visible in right photo, foreground.)





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 21

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 604 738.....

Original station number: 554.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑

Comments: Tree now is dead stump, partly burnt. Post gone
(perhaps burnt); rockspit visible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 22

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 602735

Original station number: 154

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑

Comments: Markings on tree in fairly good condition. Post gone; later 3" x 3" peg has been placed in rockspit.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 23

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 602734

Original station number: V54

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post in fairly good condition; 'T' visible (as per photo).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 24

CMA 1:25,000 map name: T. obin bille.....

Grid reference: 605725.....

Original station number: B55.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: C

Comments: Blaze has partly closed, obscuring rest of markings.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 25

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 609.714

Original station number: 155

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post rotting from below and consequently very short; rockspit intact. Nearby is what may be the stump of the former reference tree.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 25A

CMA 1:25,000 map name:.....Tidbinbilla.....

Grid reference:.....606.713.....


Original station number:.....M55.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible, rockspit in good condition (left photo). Tree
in fair condition (right photo).





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 25B

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 604713

Original station number: 055

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post gone; rockspit intact





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 26

CMA 1:25,000 map name: Tidbinbilla

Grid reference: 599708

Original station number: S55

Type of marker:

- (8" timber post, with rockspit
- (1" pipe, concreted, with nail, and rockspit
- (3" downpipe, concreted, with bolt, and rockspit
- (nail in concrete, with rockspit
- (spike in concrete, with rockspit
- (concrete block, with bolt, and rockspit
- (concrete cylinder [can formwork], with nail, and rockspit
- (old peg or post, and rockspit
- (reference tree, marked thus: 1

Comments: This marker is one of the best of its type located during the fieldwork. Left and centre photos respectively show 'CT' and 'A'; right photo shows remains of 'A' on fallen reference tree.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 27

CMA 1:25,000 map name: *Tidbinbilla*

Grid reference: *598705*

Original station number: *T55*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: *The marker itself has gone and the tree has been bulldozed or lifted quite some distance to form part of a vehicle barrier.*





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 28

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 598703.....

Original station number: 16 Mile.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Downpipe partly obscured by fallen tree, but in good condition. Very close to site 29.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 29

CMA 1:25,000 map name: Tidbinbilla.....

Grid reference: 598703.....

Original station number: V55.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post partly rotten; '↑' partly visible.....





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 30

CMA 1:25,000 map name: Corin Dam


Grid reference: 599697


Original station number: Y55

Type of marker:

- 48" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post splitting. Blaze on reference tree partly closed.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 31

CMA 1:25,000 map name: Corin Dam

Grid reference: 600 693

Original station number: A56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: The pipe (→ photo) appears to be filled, not with concrete, but with timber and the nail is anchored in that. Lovat's party may have run out of concrete here.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 32

CMA 1:25,000 map name: Corin Dam

Grid reference: 602692

Original station number: B56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: As with site 31, the pipe (→ photo) appears to be filled with timber.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 33

CMA 1:25,000 map name: Corin Dam

Grid reference: 603692

Original station number: C56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post in reasonable condition; 'A' visible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 34

CMA 1:25,000 map name: Corin Dam

Grid reference: 603 690

Original station number: D56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 1½" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: In good condition. While Mount used down-pipe for many of his mile markers, he used it less frequently for ordinary markers. This is one of several installed in the Mount Greville stretch, about the only area of his part of the border where these sorts of markers were used.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 35

CMA 1:25,000 map name: Corin Dam

Grid reference: 602 689

Original station number: 17 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe in good condition; rockspit almost entirely gone.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 36

CMA 1:25,000 map name: *Ginn Dam*


Grid reference: *601 687*

Original station number: *E56*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Good condition*





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 37

CMA 1:25,000 map name: Corin Dam

Grid reference: 602-684

Original station number: G5L

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post very rotten; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 38

CMA 1:25,000 map name: Corin Dam

Grid reference: 602687

Original station number: H56

Type of marker:

- 1/8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post very rotten (→ photo); rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 39

CMA 1:25,000 map name: Corin Dam

Grid reference: 601683


Original station number: F56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post, markings and rockspit in quite good condition. One of the better markers of this type. Blaze is visible on reference tree but markings have gone.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 40

CMA 1:25,000 map name: Corin Dam

Grid reference: 602 674

Original station number: 18 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 45

Comments: The downpipe mile marker (right photo) is in fairly good condition, though leaning at an angle. The tree's markings (left photo) are in very good condition. Additional significance is due to this type of site's rarity; as mentioned, only 3 of Mount's mile trees were found and only 2 have the marker as well.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 41

CMA 1:25,000 map name: Corin Dam


Grid reference: 605 668

Original station number: Q56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit intact.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 42

CMA 1:25,000 map name: Corin Dam.....

Grid reference: 605666.....

Original station number: T5L.....

Type of marker:

- (8" timber post, with rockspit
- (1" pipe, concreted, with nail, and rockspit
- (3" downpipe, concreted, with bolt, and rockspit
- (nail in concrete, with rockspit
- (spike in concrete, with rockspit
- (concrete block, with bolt, and rockspit
- (concrete cylinder [can formwork], with nail, and rockspit
- (old peg or post, and rockspit
- (reference tree, marked thus:

Comments: Post is lying loose on ground; '↑' visible. Rockspit gone.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 43

CMA 1:25,000 map name: Corin Dam

Grid reference: 605661

Original station number: W56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post partly rotten; 'CT' visible. Rockspit visible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 44

CMA 1:25,000 map name: Corin Dam

Grid reference: 604658

Original station number: X56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Good condition. Close to 19 mile marker (see next page).





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 45

CMA 1:25,000 map name: Corin Dam

Grid reference: 60E 658

Original station number: 19 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Good condition. The 19 Mile marker is in the background in the photo, with Site 44 in foreground.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 46

CMA 1:25,000 map name: Corin Dam


Grid reference: 603657

Original station number: Y56

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe (→ photo) in good condition. Tree (↗ photo) still shows blaze but markings gone — probably weathered off (blaze faces the direction of worst weather).





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 47

CMA 1:25,000 map name: Corin Dam

Grid reference: 603656

Original station number: 256

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Good condition





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 48

CMA 1:25,000 map name: Corin Dam


Grid reference: 610635

Original station number: 057

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 43" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 49

CMA 1:25,000 map name: Corin Dam

Grid reference: 611 634

Original station number: P57

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Good condition





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 50

CMA 1:25,000 map name: Corin Dam

Grid reference: 606624

Original station number: R57

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible, rockspit gone





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 51

CMA 1:25,000 map name: Corin Dam.....

Grid reference:..... 606624

Original station number:..... S57

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Reference tree is dead and fallen. The actual marker was not found. (Russell Weenoltz in photo)





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 52

CMA 1:25,000 map name: Corin Dam

Grid reference: 607622

Original station number: T57

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Post in fair condition. Possible fallen reference tree nearby.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 53

CMA 1:25,000 map name: Corin Dam

Grid reference: 608619

Original station number: 457

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo); rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 54

CMA 1:25,000 map name:

Corin Dam

Grid reference:

610616

Original station number:


V57

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo); rockspit in good condition.
Reference mark here was painted on adjacent boulder but
has since been weathered off.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 55

CMA 1:25,000 map name: Corin Dam

Grid reference: 613 617

Original station number: 257

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit cairn
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe is visible inside the distinctive, large
cairn seen in the photo.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 56

CMA 1:25,000 map name: Corin Dam

Grid reference: 617 607


Original station number: F58

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit largely intact.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 57

CMA 1:25,000 map name: Corin Dam


Grid reference: 618606

Original station number: 958

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo); rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 58

CMA 1:25,000 map name: Corin Dam

Grid reference: 618604

Original station number: I58

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Reference tree dead and fallen; rockspit visible.
..... pipe not visible.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 59

CMA 1:25,000 map name: Corin Dam


Grid reference: 601584

Original station number: F59

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit cairn
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible, may have gone; cairn in relatively poor condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 60

CMA 1:25,000 map name: Corin Dam

Grid reference: 603582

Original station number: I 59

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Blaze has closed up, obscuring part of the markings
(i.e. 'B' and 'C' obscured). A possible rockspit is nearby.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 61

CMA 1:25,000 map name: Corin Dam

Grid reference: 611563

Original station number: E 73

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT

Comments: Tree has fallen; markings legible.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 62

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 611559

Original station number: H73

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: pipe not visible, rockspit in reasonable condition.
Site is immediately adjacent to remnants of old border fence.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 63

CMA 1:25,000 map name: Rendezvous Creek.

Grid reference: 613.558

Original station number: I73

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit partly overgrown.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 64

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 613 557

Original station number: J73

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo); rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 65

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 613 555

Original station number: 27 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Downpipe visible; rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 66

CMA 1:25,000 map name: Rendezvous Creek


Grid reference: 607547

Original station number: P73

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible, rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 67

CMA 1:25,000 map name: *Rendezvous Creek*


Grid reference: *606547*

Original station number: *Q73*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Pipe visible; rockspit in good condition.*





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 68

CMA 1:25,000 map name: *Rendezvous Creek*

Grid reference: *603542*

Original station number: *T73*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: *Pipe visible; rockspit (↗ photo) somewhat overgrown.*
Markings on tree (↗ photo) are faint.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 69

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 603541

Original station number: 473

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 70

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 603 537

Original station number: X 73

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo); rockspit visible.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 71

CMA 1:25,000 map name: Rendezvous Creek.

Grid reference: 601537

Original station number: Y73

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe appears to have gone; rockspit in very good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 72

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 599536


Original station number: A74

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: The marker should be a 4" nail set in a concrete block, but it appears to have gone. Rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 73

CMA 1:25,000 map name: *Rendezvous Creek*

Grid reference: *620534*

Original station number: *P74*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
ct

Comments: *Markings very weathered. Tree appears to be at wrong bearing, but may be an error in the field book.*





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 74

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 601533

Original station number: E74

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fairly good condition, though partly overgrown.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 75

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 602533

Original station number: F74

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT

Comments: Pipe not visible; rockspit very overgrown by grass.
(foreground of photo). Markings on tree trunk (background
of photo).





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 76

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 602 533

Original station number: 29 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Downpipe not visible; rockspit indicated by >> in photo. Tree (→ photo) has blaze but markings gone.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 77

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 603533

Original station number: G74

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Pipe not visible; rockspit in good condition.
Markings on tree faint.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 78

CMA 1:25,000 map name: Rendezvous Creek


Grid reference: 604526

Original station number: N 74

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail not visible; rockspit in fair condition (some rocks removed).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 79

CMA 1:25,000 map name: *Rendezvous Creek*

Grid reference: *614525*

Original station number: *Y74*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *pipe not visible; rockspit partly overgrown.*





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 80

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 615524

Original station number: Z 74

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 81

CMA 1:25,000 map name: Rendezvous Creek.

Grid reference: 615524

Original station number: A 75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 82

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 616 524

Original station number: B 75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 83

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 615 523

Original station number: C75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition (in foreground of photo). In the background behind the snow gum is the Shallow Valley where Mount Party camped in the 1914-15 summer.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 84

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 616521

Original station number: D 75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo); rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 85

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 617521

Original station number: E75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 86

CMA 1:25,000 map name: Rendezvous Creek


Grid reference: 621521


Original station number: H75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.
The vanes of Bimber Td can just be seen above
the treeline in the centre of the background.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 87

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 622519

Original station number: I.75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 88

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 622579

Original station number: 31 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Down pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 89

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 623518

Original station number: K75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fair condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 90

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 625516

Original station number: L75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fair condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 91

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 626514

Original station number: 075

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Pipe visible; rockspit in good condition (left photo). Markings on tree very faint because of weathering (right photo).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 92

CMA 1:25,000 map name: *Rendezvous Creek*

Grid reference: 627513


Original station number: P.75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Pipe not visible; rockspit partly overgrown.*





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 93

CMA 1:25,000 map name: Rendezvous Creek


Grid reference: 627513

Original station number: Q75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Weathering has made the markings very faint...
Indeed.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 94

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 626512


Original station number: R75

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.
Reference tree survives but markings gone.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 95

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 621488

Original station number: 576

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible and rockspit very overgrown (» in foreground of photo). Tree (→ photo) has lost markings.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 96

CMA 1:25,000 map name:.....Rendezvous Creek

Grid reference:.....6.19.4.88.....

Original station number:.....T.76.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments:.....Pipe not visible; rockspit in fair condition,
partly overgrown.....





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 97

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 619 487

Original station number: V 76

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Part of the markings have fallen away. There appears to be paint on the surviving markings.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 98

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 619.487

Original station number: W76 *

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: The markings are worn and the 'T' has general
* The tree is at the wrong bearing for W76, but at the
correct bearing for X76 — I may be in error in calling
it W76.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 99

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 627463

Original station number: E78

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 100

CMA 1:25,000 map name: *Rendezvous Creek*

Grid reference: 628 464

Original station number: F78

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit partly overgrown.
Reference tree (» photo) has lost markings.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 101

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 629 463

Original station number: 978

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; a tree (possibly the reference tree) has fallen on part of rockspit.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 102

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 631461

Original station number: J78

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Pipe visible; rockspit in fair condition. Reference tree (» photo) has fallen but markings are visible underneath on the side facing the ground.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 103

CMA 1:25,000 map name:...Rendevous Creek

Grid reference:..... 632461

Original station number:..... K 78

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Tree is dead and fallen; part of 'C' has
gone





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 104

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 628454

Original station number: S78

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Markings on tree very clear. Pipe not visible.
rockspit only fair condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 105

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 647453

Original station number: Z 78

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit fairly good condition.
Border fence post visible in photo.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 106

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 647 452

Original station number: A79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit fair condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 107

CMA 1:25,000 map name: *Rendezvous Creek*

Grid reference: *648451*

Original station number: *B 79*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Pipe not visible; rockspit (» photo) partly overgrown. Tree has snapped off in middle of markings, leaving 'CT' on stump (→ photo). Border fence on right of photo.*





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 108

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 648450

Original station number: C 79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fair/poor condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 109

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 650448

Original station number: F 79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fair condition.
Tree fallen, markings gone.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 110

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 651 448

Original station number: 37 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit cairn
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cairn in good condition; downpipe not
obviously visible (no attempt was made to see pipe, so
as not to disturb cairn).





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 111

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 653 445

Original station number: H 79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 112

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 654 444

Original station number: I 79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fair condition.
An identical, parallel rockspit is closely adjacent (left) and evidently relates to another survey. It is one of a number of parallel markers found along the southern border during the field work.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 113

CMA 1:25,000 map name: Ruller Creek


Grid reference: 657 437

Original station number: M79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit in good condition
... the rock it has been disturbed by previous visitors some
of whom have left rubbish underneath.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 114

CMA 1:25,000 map name: Rendezvous Creek


Grid reference: 657436

Original station number: N 79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT

Comments: Pipe not visible; rockspit in fairly good condition. Tree has fallen but markings are visible.
(→ photo).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 115

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 658 434

Original station number: 38 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit cairn
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cairn in good condition; downpipe not
obviously visible (no attempt was made to see pipe, so
as not to disturb cairn).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 116

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 658434

Original station number: 079

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 117

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 660 429


Original station number: 579

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 118

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 663 426


Original station number: U79

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: The concrete cylinder has been made by using a small round can as formwork (→ photo). Rockspit is in poor condition. Drawn in the concrete on the top of can appear to be the initials 'FF'.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 119

CMA 1:25,000 map name: Yaouk

Grid reference: 675419

Original station number: 980

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: The cylinder here is formed with a rectangular can and is under the rockspit on right of photo. To left is another parallel marker including a timber peg. Such a marker is not mentioned in the field book; whether it pre- or post-dates the border survey is not known. Parts of the southern border were also ^{NSW} county, parish and portion boundaries. This and the other parallel markers found are invariably on the 'NSW side' of the border marker.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 120

CMA 1:25,000 map name: Yaovk

Grid reference:..... 676413

Original station number:..... 40 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete cylinder [can formwork], with nail, and rockspit cairn
- old peg or post, and rockspit
- reference tree, marked thus:

Comments:..... Cairn is substantial and in good condition; no attempt was made to see the cylinder—so as not to disturb cairn. A rockspit is present just to one side of the cairn.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 121

CMA 1:25,000 map name: Yaouk.....

Grid reference: 675410.....

Original station number: T80.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible, and no rockspit in fairly good condition. On left of photo is a vague parallel rockspit. A cairn (origin unknown) also stands nearby (not in photo).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 122

CMA 1:25,000 map name: *Yaduk*.....

Grid reference: *676408*.....

Original station number: *J80*.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Cylinder visible; rockspit fair condition.*





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 123

CMA 1:25,000 map name:..... Yeaule

Grid reference:..... 679407

Original station number:..... L80

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail not visible; marker? more like a cairn.....

.....

.....

.....





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 124

CMA 1:25,000 map name: Yaruk

Grid reference: 680408


Original station number: M80

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail visible (→ photo). Rockspit very
badly disturbed.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 125

CMA 1:25,000 map name: Yaouk

Grid reference: 681409

Original station number: N80

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail not visible; rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 126

CMA 1:25,000 map name: Ygouk.....

Grid reference: 682 410.....

Original station number: 080.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail visible; rockspit in good condition. (In photo, Mt Cudgenby is in the background.)





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 127

CMA 1:25,000 map name: Yeonk.....

Grid reference: 682412.....

Original station number: P80.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail not visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 128

CMA 1:25,000 map name: Yaouk


Grid reference: 682 416

Original station number: 41 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit cairn
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cairn in good condition (and was not disturbed in order to find cylinder). Another cairn, origin unknown, stands nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 129

CMA 1:25,000 map name: Yaouk

Grid reference: 682415


Original station number: Q80

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 130

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 685 423

Original station number: V80

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder appears to have gone; rockspit in fair condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 131

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 685424


Original station number: W 80

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible but has been moved (→ photo); otherwise rockspit in good condition. (Ian McLeod in photo, and behind him is cloud-shrouded Mt Bimberi).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 132

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 688433

Original station number: A81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike visible (→ photo); rockspit in fairly good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 133

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 687434

Original station number: B.81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 134

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 685 438

Original station number: C81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible (→ photo); rocksoft in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 135

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 686 440

Original station number: D81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 136

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 688440


Original station number: E81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible, rockspit in fair condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 137

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 689441

Original station number: F81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit in fairly good condition. (David Oregon in background.)





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 138

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 689441

Original station number: 681

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible (→ photo); rockspit in fair condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 139

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 689442

Original station number: H81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 140

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 690443

Original station number: I 81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible, possibly gone. Tree burnt and fallen, no markings remain.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 141

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 690 444

Original station number: J 81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 142

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 691 445

Original station number: K81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail visible; rockspit in fairly good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 143

CMA 1:25,000 map name: Rendezvous Creek.

Grid reference: 697.449

Original station number: 081

Type of marker:

- 8" timber post, with rockspit
- 4½" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; tree growing in rockspit has caused some disturbance





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 144

CMA 1:25,000 map name: Rendezvous Creek


Grid reference: 693452


Original station number: P81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: The fieldbook specifies a nail in concrete here but
.....is obviously in error as the marker is a 1" pipe (→ photo).
Rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 145

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 694 453

Original station number: Q81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail visible, rockspit in good condition. Part of
Mt. Scrubby in background of photo.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 146

CMA 1:25,000 map name: Rende... Creek

Grid reference: 698459

Original station number: R81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit cairn
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible under large cairn. The timber post is not mentioned in the field book and may have been added later. This is the summit of Mt. Kelly, which was named by Mountaineer.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 147

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 698458

Original station number: S81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 148

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 699458

Original station number: T 81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 149

CMA 1:25,000 map name: *Rendezvous Creek*

Grid reference: *703 455*

Original station number: *W81*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Pipe visible. Reference tree (» photo) has suffered fire damage and markings are gone, though some axe cuts are visible.*





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 150

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 705 454

Original station number: X 81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible. The fieldbook is in error, for it states the marker here should be a concrete cylinder. Rockspit in fairly good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 151

CMA 1:25,000 map name: *Rendezvous Creek*


Grid reference: *706452*

Original station number: *Y 81*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Cylinder visible (→ photo); rockspit in good condition.*





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 152

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 707451

Original station number: Z 81

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible (→ photo); rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 153

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 708450

Original station number: 482

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 154

CMA 1:25,000 map name: *Rendezvous Creek*.

Grid reference: *709447*

Original station number: *B82*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Cylinder not visible; some disturbance to rockspit.*





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 155

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 711441

Original station number: D82

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 156

CMA 1:25,000 map name: Rendezvous Creek.

Grid reference: 707434


Original station number: 682

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit disturbed by growing tree.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 157

CMA 1:25,000 map name: Rendezvous Creek.

Grid reference: 708431

Original station number: T82

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 158

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 70 9475

Original station number: K82

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike visible; rockspit in good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 159

CMA 1:25,000 map name: Rendezvous Creek

Grid reference: 711424

Original station number: L 82

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike visible (→ photo); rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 160

CMA 1:25,000 map name: Rendezvous Creek


Grid reference: 744472.1

Original station number: M.82

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 161

CMA 1:25,000 map name: Ygouk.....

Grid reference: 711.418.....


Original station number: N 82.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in very good condition;
an excellent example of this type of marker.
(ML Kelly at right of photo.)





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 162

CMA 1:25,000 map name: Yaouk.....

Grid reference: 712417.....

Original station number: 082.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo), i rocks & overgrown
and fairly poor.....





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 163

CMA 1:25,000 map name: Yaroule

Grid reference: 714 418

Original station number: P. 82

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit partly overgrown. A timber post (similar to that at R81) is lying across the rockspit — its origins are unknown.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 164

CMA 1:25,000 map name: Yarruk.....

Grid reference: 716417.....


Original station number: Q 82.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible (→ photo); rockspit in fairly good condition.....
.....
.....





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 165

CMA 1:25,000 map name: Yaruk.....

Grid reference: 716 417.....

Original station number: R. 82.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.
Mt. Gudgenby summit on left of photo.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 166

CMA 1:25,000 map name: Yaouk.....

Grid reference: 716400.....


Original station number: H.83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit fair. Reference tree
blaze has been burnt and markings are gone.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 167

CMA 1:25,000 map name:..... Yaoule.....

Grid reference:..... 716 399

Original station number:..... T 83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit far. Blaze on
tree has been burnt and markings have gone.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 168

CMA 1:25,000 map name: Yeaule

Grid reference: 714398


Original station number: J83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit fair. Reference tree
has been burnt and stump remains.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 169

CMA 1:25,000 map name: Yaruk

Grid reference: 714-398

Original station number: 49 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit cairn
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cairn in good condition; it was not disturbed
in order to find pipe.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 170

CMA 1:25,000 map name: Yaouk

Grid reference: 713397

Original station number: K83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition
and is distinctive for being made of amatz.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 171

CMA 1:25,000 map name: Yaank.....


Grid reference: 712 397.....

Original station number: L83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit disturbed by growing trees. Blaze on reference tree has rotted and markings have gone.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 172

CMA 1:25,000 map name: Yaouk.....

Grid reference: 712 396.....

Original station number: M83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in good condition. Blaze
on tree has closed.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 173

CMA 1:25,000 map name:.....*Yarralumla*.....

Grid reference:.....*712394*.....

Original station number:.....*N.83*.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments:.....*Pipe not visible; rockspit in good condition.*.....





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 174

CMA 1:25,000 map name: Yarwuk

Grid reference: 712392

Original station number: 083

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 175

CMA 1:25,000 map name: Yaouk.....

Grid reference: 712389.....

Original station number: P.83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑

Comments: Pipe not visible; rockspit in good condition.
Reference tree has been burnt and some of the markings
have been lost as a result.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 176

CMA 1:25,000 map name: Yaruk

Grid reference: 711389

Original station number: Q 83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit of particular interest for its "split level" nature, with some stones placed on top of other borders as seen towards rear in photo.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 177

CMA 1:25,000 map name: Yarrawa


Grid reference: 713287

Original station number: R83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; a lyrebird has made its mound
in centre of rockspit. At vegue parallel rockspit is
nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 178

CMA 1:25,000 map name: Yarrawa.....

Grid reference: 712 385.....


Original station number: RA 83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit fairly good condition.
Vague parallel rockspit nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 179

CMA 1:25,000 map name: Yeaulek

Grid reference: 713384

Original station number: R.G. 83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 180

CMA 1:25,000 map name: Yowk

Grid reference: 713383

Original station number: 50 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit cairn
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cairn in good condition; it was not disturbed
in order to locate pipe inside.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 181

CMA 1:25,000 map name: Yaouk.....

Grid reference: 713383.....

Original station number: S83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in fair condition.....
..... Another of the parallel rockspits is at this site,
..... complete with a burnt timber peg just visible to -
..... wards rear of the photo(?)





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 182

CMA 1:25,000 map name: Yaouk.....

Grid reference: 712 381.....

Original station number: T 83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit fair.....





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 183

CMA 1:25,000 map name: Yaouk

Grid reference: 712 380

Original station number: U.83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit in fairly good condition. On the left of the photo can be seen a parallel rockspit with timber peg which is partly burnt.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 184

CMA 1:25,000 map name: Yowak.....


Grid reference: 712 379.....

Original station number: V 83.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.
To right of photo is a parallel marker with small
timber peg. As previously mentioned, these parallel marks
are invariably on the NSW side of the border marker.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 185

CMA 1:25,000 map name: Yaowk

Grid reference: 713375

Original station number: Y.83

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.
A parallel rockspit is also at the site, out of photo.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 186

CMA 1:25,000 map name: Yaouk

Grid reference: 714372

Original station number: A 84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.
A parallel rockspit with small timber peg is also at
the site.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 187

CMA 1:25,000 map name: Yaouk.....

Grid reference: 714-371.....

Original station number: B 84.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit fair.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 188

CMA 1:25,000 map name: Yaonk

Grid reference: 715370

Original station number: C 84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Pipe visible; rockspit in fairly good condition.
Markings on reference tree quite legible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 189

CMA 1:25,000 map name: Yaouls.....

Grid reference: 714369.....

Original station number: D 84.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit fair. The marker is in centre and left of photo, while to right is parallel rockspit with small timber peg. As mentioned, it is not known if these parallel markers pre- or post-date the border survey. Parts of the southern border were variously NSW county, parish and portion boundaries.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 190

CMA 1:25,000 map name: Yaruk

Grid reference: 713367

Original station number: 51 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit Cairn
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cairn in good condition; it was not disturbed in order to find pipes.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 191

CMA 1:25,000 map name: Yassuk.....

Grid reference: 713367.....

Original station number: E84.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit fair. Part of the reference tree blaze has been overgrown, obscuring them't'. A parallel rockspit is nearby.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 192

CMA 1:25,000 map name: Yaovk

Grid reference: 712366

Original station number: F84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit far. A parallel rockspit is nearby.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 193

CMA 1:25,000 map name: Yerowie

Grid reference: 711365

Original station number: H84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit far. A parallel rockspit
is nearby.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 194

CMA 1:25,000 map name: Yaouk

Grid reference: 709364

Original station number: J84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Pipe not visible; rockspit in good condition. Tree markings in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 195

CMA 1:25,000 map name: *Yarwuk*


Grid reference: *709362*

Original station number: *K.84*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Cylinder visible; part of a tree has fallen on rockspits. A parallel rockspit (and timber peg) is nearby.*





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 196

CMA 1:25,000 map name: Yowak

Grid reference: 709361

Original station number: L84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT

Comments: Tree dead but markings quite legible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 197

CMA 1:25,000 map name: Yaowle

Grid reference: 707360


Original station number: M84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible, rockspit in good condition.
Parallel rockspit nearby.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 198

CMA 1:25,000 map name: *Yaowk*

Grid reference: *707.359*

Original station number: *N.84*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Pipe visible; rockspit in good condition.*
Parallel rockspit nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 199

CMA 1:25,000 map name: Yarrawa.....

Grid reference: 706357.....

Original station number: 084.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.
Parallel rockspit nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 200

CMA 1:25,000 map name: Yaouk

Grid reference: 706 356

Original station number: P. 84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible (its formwork being one of the rarer rectangular, not round, cans); tree has fallen on rockspit. A parallel rockspit and peg are nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 201

CMA 1:25,000 map name: Yarwuk

Grid reference: 705355

Original station number: Q84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: The border marker is in centre of photo; the pipe is visible to right, up against boulder, is parallel rockspit with timber peg.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 202

CMA 1:25,000 map name: Yarwuk

Grid reference: 704354

Original station number: 52 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit cairn
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: A tree has fallen onto cairn; no attempt was made to see pipe inside cairn. Reference tree has been burnt and the blaze is mostly closed.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 203

CMA 1:25,000 map name: Yarck

Grid reference: 704354

Original station number: R 84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in good condition.
Parallel rockspit with small timber peg are nearby and
as usual are on NSW side of border marker.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 204

CMA 1:25,000 map name: Yaouk.....

Grid reference: 704354.....

Original station number: 584.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit fair (to left of centre of photo). To right of photo is parallel rockspit and peg.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 205

CMA 1:25,000 map name:..... Yaouk

Grid reference:..... 703 353

Original station number:..... T 84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible, rockspit in fairly good condition.
Parallel rockspit nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 206

CMA 1:25,000 map name: Yaouk

Grid reference: 704352

Original station number: U.84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible — fallen tree on rockspit.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 207

CMA 1:25,000 map name:..... Yaowk

Grid reference:..... 704352

Original station number:..... V.84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fair condition.
Parallel rockspit nearby.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 208

CMA 1:25,000 map name: Yaouk.....

Grid reference: 705 351.....

Original station number: W 84.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Pipe visible. The fieldbook gives the bearing from the reference tree, rather than to the tree from the marker. Parallel rockspit nearby.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 209

CMA 1:25,000 map name:..... Yaowk

Grid reference:..... 707348

Original station number:..... X 84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 210

CMA 1:25,000 map name: Yaouk

Grid reference: 708347

Original station number: Y84

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in fair condition





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 211

CMA 1:25,000 map name: Yaouk.....

Grid reference: 711345.....

Original station number: C 85.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition...





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 212

CMA 1:25,000 map name: Yaouk


Grid reference: 712 345

Original station number: D. 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: The field book / FC 18 chart does not indicate the type of marker here; what remains is a fragmented rockspit.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 213

CMA 1:25,000 map name: Yaouk

Grid reference: 713304

Original station number: E 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail visible (→ photo); rockspit in fairly good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 214

CMA 1:25,000 map name: Yaruk

Grid reference: 713344

Original station number: 53 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit cairn
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible (→ photo); cairn small.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 215

CMA 1:25,000 map name: Yarook

Grid reference: 713341

Original station number: F85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.
In photo, Sentry Box Rock is just left of centre in background, with Mt Kelly just to the left and Mt Budgenby off to the right.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 216

CMA 1:25,000 map name: Yaouk

Grid reference: 713338

Original station number: 9.85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.
Yaouk valley in background of photo, with approaching
snow clouds in distance.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 217

CMA 1:25,000 map name: Ygouk

Grid reference: 713336

Original station number: H 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail visible; rockspit in quite good condition.
The larger rock outcrop in right background is what Mount
described in his field book as 'isolated precipitous peak'





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 218

CMA 1:25,000 map name: Yauuk


Grid reference: 717.335

Original station number: J 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible, rockspit in good condition.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 219

CMA 1:25,000 map name: Yaouk

Grid reference: 718 335

Original station number: K 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike visible (→ photo); rockspit partly disturbed.
This marker is the apex of two "triangles" surveyed along
here by Mount. Neither apex is on the border ITSELF but
they are included in the alpha-numeric border marker
numbering system and so this one is included in the inventory.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 220

CMA 1:25,000 map name: Yarouk

Grid reference: 708335

Original station number: L 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit largely overgrown.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 221

CMA 1:25,000 map name: Yaouk

Grid reference: 721 333

Original station number: M 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike visible; rockspit notable for very long, large stones.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 222

CMA 1:25,000 map name: *Yarouk*


Grid reference: *721333*

Original station number: *54 Mile*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit cairn
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *Cylinder visible in cairn in good condition.*





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 223

CMA 1:25,000 map name: Yaovk

Grid reference: 722332

Original station number: 0.85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 224

CMA 1:25,000 map name: Yaouk

Grid reference: 721328

Original station number: P. 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit notable for its
inaccessibility (on top of big granite outcrop/ boulder with
only about one handhold to assist climbing).





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 225

CMA 1:25,000 map name:..... Yaouk.....

Grid reference:..... 719327

Original station number:..... Q 85

Type of marker:


- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:


Comments:..... Cylinder visible, rockspit in fairly good condition.

.....

.....

.....





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 226

CMA 1:25,000 map name: Yauk


Grid reference: 719326

Original station number: R 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 227

CMA 1:25,000 map name: Yarouk

Grid reference: 718324

Original station number: U.85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit partly overgrown.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 228

CMA 1:25,000 map name: Yaruk

Grid reference: 718323

Original station number: V 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 229

CMA 1:25,000 map name: Yaruk

Grid reference: 719321

Original station number: X 85

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit fair.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 230

CMA 1:25,000 map name: Yaouk.....

Grid reference: 720314.....

Original station number: 686.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; tree has fallen on rockspit.....





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 231

CMA 1:25,000 map name: Yaouk

Grid reference: 722312


Original station number: J86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑

Comments: Pipe visible; rockspit in fairly good condition.
Reference tree has been burnt and has fallen.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 232

CMA 1:25,000 map name: Yaouk

Grid reference: 722 311


Original station number: K 86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 233

CMA 1:25,000 map name: Yarwuk


Grid reference: 722310

Original station number: L 86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT

Comments: Markings faint, as per photo. Tree long dead.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 234

CMA 1:25,000 map name: Yarwuk

Grid reference: 722308


Original station number: N.86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: C

Comments: Blaze has closed, leaving only part of the original markings visible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 235

CMA 1:25,000 map name: Yassuk

Grid reference: 723305

Original station number: P86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit in good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 236 + 237

CMA 1:25,000 map name: Yaouk

Grid reference: 723304

Original station number: 56 Mile + R86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
at

Comments: The 56 Mile cairn is at left of photo (and was not disturbed in order to find piece); at right is R86 rockspit, cylinder visible. The reference tree has fallen.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 238

CMA 1:25,000 map name: *Yankee*

Grid reference: *724304*

Original station number: *S 86*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: *Small part of markings obscured by partial closure
of blaze.*





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 239

CMA 1:25,000 map name: Yaouk

Grid reference: 726 302

Original station number: W 86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit notable for large size
of stones





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 240

CMA 1:25,000 map name: Yaank.....

Grid reference: 728302.....

Original station number: X86.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rocks & somewhat overgrown.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 241

CMA 1:25,000 map name: Yaduk

Grid reference: 729302

Original station number: Y86

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spike not visible; rockspit slightly disturbed.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 242

CMA 1:25,000 map name: Yaouk.....


Grid reference: 731301.....


Original station number: Z86.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; a tree has fallen on rockspit.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 243

CMA 1:25,000 map name: Yaouk.....

Grid reference: 733300.....


Original station number: B87.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Cylinder visible; rockspit in good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 244

CMA 1:25,000 map name: Yaouk

Grid reference: 733298

Original station number: C87

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: 

Comments: Good example of a reference tree as cut by Mount's party.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 245

CMA 1:25,000 map name: Yaouk

Grid reference: 732 296

Original station number: E 87

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit partly overgrown





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 246

CMA 1:25,000 map name: Yarouk

Grid reference: 736293

Original station number: 487

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe not visible; rockspit in generally good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 247

CMA 1:25,000 map name: Yaunk


Grid reference: 744286

Original station number: R 87

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Spikes not visible; Mourat's rockspit is presumably that on left of photo. To right of centre is another of the parallel rockspits found during the field work and which are invariably on the N.E. side of the border marker. Mourat's marker is the last one instated by his party before meeting with Johnston's party.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 248

CMA 1:25,000 map name: Yaouk.....

Grid reference:.....7AA 283.....

Original station number:.....A43*.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: *This is a confusing site. Although the fieldbook indicates a pipe, field work located two timber markers here, within a few metres of each other. That on right shows the NSW Survey drawn (the peg is upside down on rockspit) and may pre-date the border survey. The pipe was not found.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 249

CMA 1:25,000 map name: Shannons Flat

Grid reference: 743282

Original station number: Z 42*

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: * This site too is confusing. Johnston's field book states "old post on top granite rock replaced by bolt in concrete". But fieldwork failed to find bolt but did find timber peg/post and rockspit as per photo. It is possible that the site found is that which Johnston found and perhaps the bolt was not put in. The rockspit is disturbed. The site may predate the border survey and relate to earlier NSW parish or portion surveys.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 250

CMA 1:25,000 map name: Shannons Flat

Grid reference: 748280

Original station number: V 42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit poor. No sign of blaze on tree — presumably it has closed.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 251

CMA 1:25,000 map name: Shannons Flat

Grid reference: 748 280


Original station number: 1 1/2 Mile

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: $\frac{1}{12}$

Comments: Significant as the only one of Johnston's mile trees located during the fieldwork. The distance is that from Coome via the northern and eastern borders of the ACT.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 252

CMA 1:25,000 map name: Shannons Flat

Grid reference: 752276


Original station number: R 42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: C
R

Comments: Pipe visible; rockspit in good condition. Reference tree is dead and fallen; much of the original marking has been lost. Johnston (in contrast to Mount) marked his trees with the station number as well as the 'A' and 'CT' markings. This tree originally therefore was marked: A
CT
R 42





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 253

CMA 1:25,000 map name: Shannons Flat

Grid reference: 753274

Original station number: Q42

Type of marker:


- 8" timber post, with rockspit
- 2" pipe, concreted, with nail, and rockspit cairn
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

$\frac{1}{2}$
 $\frac{2}{3}$
 $\frac{3}{4}$

Comments: Pipe visible, with cairn. The tree is dead and fallen and blaze is partly closed. Original markings were:

$\frac{1}{2}$
CT
Q42





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 254

CMA 1:25,000 map name: Shannons Flat

Grid reference: 754273

Original station number: P 42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit cairn
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT
P 42

Comments: Pipe not visible, cairn shown in lower photo. Upper photo shows tree which is dead and fallen, though markings still quite legible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 255

CMA 1:25,000 map name: Shannons Flat

Grid reference: 755 272

Original station number: N42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit not wholly intact. Possible second rockspit on NSW side of marker, nearby (in rear of photo).





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 256

CMA 1:25,000 map name: Shannons Flat

Grid reference: 757 270

Original station number: L42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit cairn
- reference tree, marked thus: L42

Comments: Old post gone, cairn remains. Reference tree blaze
partly grown over, leaving only a remnant of the markings,
as shown above (i.e. lost).





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 257

CMA 1:25,000 map name:....Shannons Flat.....

Grid reference:....757269.....


Original station number:.....K 42*.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: * This site too is confusing. Johnston's fieldbook states that the marker was an old post. The post has gone, but two cones, either one of which could mark the site of the post, remain, one in foreground of left photo and one in right photo. Yet there is also a 1" pipe (left photo) which is not mentioned in the field book, and for which no explanation can be given; it is the same sort of pipe used by the border surveyors.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 258

CMA 1:25,000 map name: Shantons Flat

Grid reference: 758268

Original station number: J 42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit cairn
- reference tree, marked thus:

Comments: The post (part of the old log fence line) remains, though it has fallen. It has a cairn at its base.





ACT BORDER SURVEY — SITE INVENTORY FORM

Site no. 259

CMA 1:25,000 map name: Shannons Flat

Grid reference: 760257

Original station number: I42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit cairn
- reference tree, marked thus:

Comments: Post gone, but cairn remains. Blaze on reference tree has closed.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 260

CMA 1:25,000 map name: Shannons Flat

Grid reference: 76.1266

Original station number: H42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit cairn
- reference tree, marked thus: C
H4

Comments: Old post gone, cairn remains. The reference tree blaze is partly obscured, covering part of markings which originally were A C H42.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 261

CMA 1:25,000 map name: Sherman Flat

Grid reference: 763 264

Original station number: 942


Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit

old peg or post, and rockspit
 reference tree, marked thus:

↑
CT
G42

Comments: Old post gone; rockspit remains. The tree is a very good example of one of Towns' trees, the markings including the station numbers.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 262

CMA 1:25,000 map name: Shannons Flat

Grid reference: 764264

Original station number: F42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit cairn
- reference tree, marked thus:

Comments: Old post gone; cairn in good condition. Reference tree has fallen, no markings visible.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 263

CMA 1:25,000 map name: Shannons Flat

Grid reference: 765263

Original station number: E42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus: ↑
CT
E42

Comments: Pipe not visible; rockspit remains. Reference tree
is a good example of one of Johnston's trees





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 264

CMA 1:25,000 map name: Shannon Flat.....

Grid reference:.....766260.....

Original station number:.....B42.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 265

CMA 1:25,000 map name: Shannons Flat

Grid reference: 76.8.258


Original station number: A.42

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Nail (pin) not visible; rockspit in fair condition. Markings not extant on tree. Note: this is site 945 in vol. 9 of the Sites of Significance series. The tree and piece of attached timber included in that volume are not part of the original border survey, nor is the piece of timber aligned with the border. This consequently affects the National Trust's ACT register of heritage sites.





ACT BORDER SURVEY—SITE INVENTORY FORM

Site no. 266

CMA 1:25,000 map name: Shannons Flat

Grid reference: 773255

Original station number: V 41

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe appears to have gone and to have been replaced / superseded by a later indication stake. The rockspit remains.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 267

CMA 1:25,000 map name: Shannons Flat

Grid reference: 774256

Original station number: U41

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible; rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 268

CMA 1:25,000 map name: Shannons Flat

Grid reference: 777 259

Original station number: Q41

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe visible (→ photo); rockspit in fairly good condition.





ACT BORDER SURVEY— SITE INVENTORY FORM

Site no. 269

CMA 1:25,000 map name:....Shannons Flat.....

Grid reference:.....785259.....

Original station number:.....K.41.....

Type of marker:

- 8" timber post, with rockspit
- 1" pipe, concreted, with nail, and rockspit
- 3" downpipe, concreted, with bolt, and rockspit
- nail in concrete, with rockspit
- spike in concrete, with rockspit
- concrete block, with bolt, and rockspit
- concrete cylinder [can formwork], with nail, and rockspit
- old peg or post, and rockspit
- reference tree, marked thus:

Comments: Pipe probably gone; rockspit in fairly good condition. A later star picket has been placed over the site by a subsequent surveyor; attached to its top is a tag reading 'K41' (→ photo).

